

SPARK PLUG REPAIR KIT M14X1.25

M14X1.25

www.autofast.co.za

Tel : 0217052101

Fax : 0866962277

Email : ztclips@gmail.com



Contents :

Part #	Description	Quantity	Price	Total
TS1412508	HELICOIL M 4 X 0.7 X 1.5D	10	R 31.25	R 312.50
TS1412509	HELICOIL M 5 X 0.8 X 1.5D	10	R 32.90	R 329.00
TS14125168	HELICOIL M 6 X 1.0 X 1.5D	10	R 34.60	R 346.00
SC14125	HELICOIL M 8 X 1.25 X 1.5D	10	R 24.95	R 249.50
SC14125FLANGED	HELICOIL M10 X 1.25 X 1.5D	5	R 35.15	R 175.75
HE14X1.25X1.0D	HELICOIL M10 X 1.5 X 1.5D	10	R 7.45	R 74.50
HE14X1.25X1.5D	HELICOIL M12 X 1.25 X 1.5D	10	R 8.40	R 84.00
HE14X1.25X2.0D	HELICOIL M12 X 1.5 X 1.5D	10	R 8.60	R 86.00



INCLUDES FREE BIN VALUED AT R290.00

PART NUMBER : SPK76

R 1 657.25

excluding VAT, while stock lasts